

## 518 W. 111th Street Interior Renovation

olumbia University is performing an interior renovation at 518 W. 111th Street, a residence building for graduate students and faculty. The building had significant water damage due to ongoing plumbing issues and the interior needs to be renovated to correct those issues. The project includes a building-wide replacement of the floor structures; structural work in the basement; repairs of the parapets; new mechanical, electrical, and plumbing systems; new interior finishes; and new fire protection systems.

# Upcoming Street Closure of W. 111th Street – Tuesday, July 30

### What is Happening

The crane pick scheduled for Thursday, July 25 has been rescheduled to take place on Tuesday, July 30. This work will require a full closure of W. 111th Street between Broadway and Amsterdam Ave. from 7:00 a.m. to 3:00 p.m. to bring two HVAC units to the roof of 518 W. 111th Street.

NOTE: Activities are subject to change based on weather and other field conditions.

### What to Expect

- A full street closure of W. 111th Street between Broadway and Amsterdam Avenue will occur on Tuesday, July 30 between 7:00 a.m. to 3:00 p.m.
- A flag person will be stationed at Amsterdam Avenue to redirect traffic.
- Additional periodic closures of W. 111th Street may occur when materials are delivered into the building.
- Expect noise and other impacts typically associated with construction projects.

#### For More Information

If you have any questions or concerns, please call the Columbia University Facilities Services Center at (212) 854-2222, 24 hours a day, seven days a week, or email <a href="mailto:projx@columbia.edu">projx@columbia.edu</a> (emails responded to during normal business hours). We apologize for the inconvenience and thank you for your patience while we perform this work.